

## Y: Engine Oil Temperature (EOT) Sensor

[← Y: Introduction](#)

### Y1 DIAGNOSTIC TROUBLE CODE (DTC) 0198

- DTC 0198 indicates EOT sensor circuit out of range high.
- Possible causes:
  - Open in harness
  - Damaged connection
  - Damaged EOT sensor
  - Damaged PCM
- Key off.
- Disconnect suspect EOT sensor and inspect connector terminals for damage. Repair if necessary.
- Measure resistance from Pin A to ground.

#### Is resistance less than 5 ohms?

Yes	No
GO to <a href="#">Y2</a> .	REPAIR open in signal return circuit. CLEAR DTCs and RETEST.

### Y2 INDUCE OPPOSITE FAILURE

- Key on/engine off.
- Jumper Pin A to Pin B at harness connector.

#### Is DTC 0197 present?

Yes	No
REPLACE EOT sensor. CLEAR DTCs and RETEST.	GO to <a href="#">Y3</a> .

### Y3 CHECK CONTINUITY OF SENSOR SIGNAL AND SIG RTN CIRCUITS

- Key off.
- EOT sensor disconnected.
- Disconnect PCM. Inspect for damaged or pushed-out pins, corrosion, loose wires, etc. Service as necessary.
- Install breakout box. Leave PCM disconnected.
- Measure resistance between harness connector Pin B and Test Pin 38 (EOT) at the breakout box.

#### Is each resistance less than 5 ohms?

Yes	No
REPLACE PCM. REMOVE breakout box. CLEAR DTCs and RETEST.	SERVICE open in signal circuit. CLEAR DTCs and RETEST.

**Y4 DIAGNOSTIC TROUBLE CODE (DTC) 0197: INDUCE OPPOSITE DTC 0198**

- DTC 0197 indicates EOT sensor circuit out of range low.
- Possible causes:
  - Grounded circuit in harness
  - Damaged EOT sensor
  - Damaged PCM
  - Damaged connection
- Key off.
- Disconnect vehicle harness from EOT sensor. Inspect for damaged, corroded, pushed-out pins or loose wires, etc. Service as necessary.
- Run KOEO Self Test.

**Is DTC 0198 present?**

Yes	No
REPLACE EOT sensor. RECONNECT harness. RERUN Scan Tool Diagnostic Test.	GO to <a href="#">Y5</a> .

**Y5 CHECK TEMPERATURE SENSOR SIGNAL CIRCUIT FOR SHORT TO GROUND**

- Key off.
- Suspect temperature sensor disconnected.
- Disconnect PCM. Inspect for damaged or pushed-out pins, corrosion, loose wires, etc. Service as necessary.
- Install breakout box. Leave PCM disconnected.
- Measure resistance between Test Pin 38 (EOT) and Test Pins 25, 51, 76, 77, 91 and 103.

**Is each resistance greater than 10,000 ohms?**

Yes	No
REPLACE PCM. REMOVE breakout box. CLEAR DTCs and RETEST.	SERVICE short to ground circuit. REMOVE breakout box. CLEAR DTCs and RETEST.

**Y6 CONTINUOUS MEMORY DIAGNOSTIC TROUBLE CODE (DTC) 0198, OR 0197: CHECK SENSOR**

- Continuous Memory DTC 0198 indicates EOT sensor circuit out of range high. The DTC was generated under normal driving conditions.
- Continuous Memory DTC 0197 indicates EOT sensor circuit out of range low. The DTC was generated under normal driving conditions.

Sensors	Continuous Memory DTCs
EOT	0198 and 0197

- Possible causes:
  - Worn or damaged EOT sensor
  - Open circuit in harness
  - Grounded circuit in harness
  - Worn or damaged PCM

- Key on/engine off.
- Access EOT PID.
- Tap on EOT sensor to simulate road shock, wiggle harness connector while observing NGS Tester value.

**Does EOT sensor value default to 100°C (212° F)?**

Yes	No
GO to <a href="#">Y9</a> .	GO to <a href="#">Y7</a> .

**Y7 CHECK VEHICLE HARNESS**

- Key on, engine off.
- Access EOT PID.
- Grasp the vehicle harness close to the EOT sensor connector. Wiggle, shake harness while working towards the PCM.

**Does EOT sensor value default to 100°C (212° F)?**

Yes	No
REPAIR circuit as required.	GO to <a href="#">Y8</a> .

**Y8 CHECK PCM AND VEHICLE HARNESS CONNECTORS**

- Key off.
- Disconnect PCM. Inspect for damage, loose or pushed-out pins, loose or poorly crimped wires.

**Are connectors and terminals OK?**

Yes	No
Unable to duplicate and/or identify concern at this time. CLEAR DTCs and RETEST.	SERVICE as necessary. CLEAR Continuous Memory and RETEST.

**Y9 INSPECT CONNECTOR PINS**

- Disconnect harness connector.
- Inspect pins.

**Is a fault detected?**

Yes	No
REPAIR damaged pins as required. CLEAR DTCs and RETEST.	REPLACE EOT sensor. CLEAR DTCs and RETEST.

**Y10 DIAGNOSTIC TROUBLE CODE (DTC) 0196 OR 0195: CHECK OPERATION, INSTALLATION OF EOT SENSOR**

- DTC 0196 or 0195 indicates that the engine oil temperature is not warm enough to perform a KOER Cylinder Contribution Self Test. The engine oil temperature must be greater than 74°C or 165° F (1.37 volts).
- Possible causes:
  - Engine not fully warmed up
  - Low oil level
  - Worn or damaged EOT sensor
  - Faulty thermostat
  - EOT sensor circuit failure
- Verify no KOEO DTCs are present.
- Drive vehicle until thermostat opens.
- Fully warm engine.
- Check that upper radiator hose is hot and pressured.
- Rerun Scan Tool Diagnostic Test.

**Is DTC 0196 or 0195 present?**

Yes	No
GO to <a href="#">Y11</a> .	SERVICE other DTCs as necessary.

**Y11 EOT SENSOR CHECK**

- Key on/engine off.
- Engine at normal operating temperature.
- Access EOT PID on NGS Tester.
- Observe EOT PID while tapping on EOT sensor.

**Does EOT valve fluctuate or go below 74°C or 165° F (1.37 volts)?**

Yes	No
REPLACE EOT sensor. CLEAR DTCs and RETEST.	GO to <a href="#">Y12</a> .

**Y12 CHECK VEHICLE HARNESS**

- Observe EOT PID valve on NGS Tester while performing the following:
- Grasp the vehicle harness close to the EOT sensor connector, wiggle, shake vehicle harness while working towards PCM.

**Does valve fluctuate?**

Yes	No
REPAIR circuits as required. CLEAR DTCs and RETEST.	GO to <a href="#">Y13</a> .

**Y13 CHECK PCM AND VEHICLE HARNESS CONNECTOR**

- Key off.
- Disconnect EOT sensor connector.

- Disconnect PCM.
- Inspect for damage, loose or pushed-out pins.

**Are connectors and terminals OK?**

Yes	No
Unable to duplicate and/or identify concern at this time. CLEAR DTCs and RETEST.	SERVICE as required. CLEAR DTCs and RETEST.

---