

<ul style="list-style-type: none"> • INSTRUMENT PANEL—LOOSE RIGHT HAND ATTACHMENT TO COWL SIDE • NOISE—“RATTLE” COMING FROM RIGHT SIDE OF INSTRUMENT PANEL 	Article No. 94-15-13
--	---------------------------------

FORD: 1992-1994 BRONCO, F SUPER DUTY, F-150-350 SERIES

ISSUE

A “rattling” noise may come from the right hand side of the instrument panel. This occurs when the cowl attachment cracks causing the instrument panel to become loose.

ACTION

Install a metal bracket to the right side of the instrument panel to secure instrument panel to cowl. Refer to Instruction Sheet #6551.

Service Kit (F4TZ-1504366-A) consists of:

- One (1) bracket
- Three (3) rivets
- One (1) Instruction Sheet #6551

PART NUMBER	PART NAME
F4TZ-1504366-A	Instrument Panel Service Kit

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
941513A	Install Bracket	1.0 Hr.

DEALER CODING

BASIC PART NO. 04366	CONDITION CODE 01
-------------------------	-------------------------

OASIS CODES: 107000, 702300