

CALIFORNIA WARRANTY BUYBACK NOTICE

Y797

P7263

(Check One)

☐ This vehicle was repurchased by the vehicle's manufacturer after the last retail owner or lessee requested its repurchase due to the problem(s) listed below.

☒ **THIS VEHICLE WAS REPURCHASED BY ITS MANUFACTURER DUE TO A DEFECT IN THE VEHICLE PURSUANT TO CONSUMER WARRANTY LAWS. THE TITLE TO THIS VEHICLE HAS BEEN PERMANENTLY BRANDED WITH THE NOTATION "LEMON LAW BUYBACK."** Under California law, the manufacturer must warrant to you, for a one year period, that the vehicle is free of the problem(s) listed below.

V.I.N.	Year	Make	Model
1FTWW31P5 5EB29531	2005	FORD	F-Series

Problem(s) Reported by Original Owner	Repairs Made, if any, to Correct Reported Problem(s)
NO CRANK START TEMP ALL ENGINE TEMP OIL SYSTEM LEAKS ENGINE BLOCK	<i>Rav Insp</i> <i>Retune Rear Bles</i> <i>Repl Vsc Hub Switch</i> <i>Repl FT Grill</i> <i>Installed Stock Exhaust,</i>

**** THE REACQUIRED VEHICLE REPAIR HISTORY SUMMARY IS ATTACHED ****

Signature of Manufacturer

Signature of Dealer(s)

11/3/04
Date

Date

Signature of Retail Buyer or Lessee

Date