

CONT CODES PASSES GEM CODE P1878 RETURNED AFTER CLEARED ISOLATED CONCERN TO PVH NO GOOD REPLACED PVH CONTROLLER

12-AUGUST-2011

DEALER: Folsom Lake Ford, Inc.

WARRANTY CLAIM NUMBER: 621065

ODOMETER: 060906M

PART NUMBER	PART DESCRIPTION	QUANTITY	LABOR OP	CONDITION CODE	CONDITION DESC
6C3Z 8200EAA	RADIATOR GRILLE	001	8200A	42	DOES NOT OPERATE PROPERLY

REPLACED FRPONT GRILL

12-JULY-2011

DEALER: Future Ford Lincoln

WARRANTY CLAIM NUMBER: 758292

ODOMETER: 056800M

PART NUMBER	PART DESCRIPTION	QUANTITY	LABOR OP	CONDITION CODE	CONDITION DESC
BXT 66860	MOTORCRAFT BATTERY	000	10654C	42	DOES NOT OPERATE PROPERLY
		000	10654C1		

VERIFIED THAT THE BATTERY IS BAD. PULLED CODES AND REPLACED THE BATTERY. CC AS - 850 DTC - 02WMA 3J3J0 980 ACES - XG41K

[Click Here for Full Warranty History](#)

On-line 1878

END OF OASIS REPORT FOR 1FTWW31P55EB29531

© Copyright 2002-2012 Ford Motor Company. All rights reserved.